



PEUGEOT 5008: 1FRQ817

Vinnnumber:	VF30E9HD8DS176194	Versionname:	5008 e-HDi Active FAP BMP 115PK Aut.
First Registrationdate:	3/10/2013	Fiscalpower:	
Expertise Mileage:	175447	Power Kw:	84
Bodytype:	MPV	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4324
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/97 H LightMetal			
Winter tyres:	Fr.L.	Fulda: 7,5 mm	Fr.R.	Fulda: 7,5 mm
	Re.L.	Fulda: 8 mm	Re.R.	Fulda: 8 mm

Assistance equipment


Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT 2079,76

Outer backrest protection L, Scratch(es), E - Replace 35,00




Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Scratch(es), LI - Repair and paint (complete) 301,68



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover F L, Stain, Cleaning 25,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Not functioning (well), Repair/replace (lump sum) 0,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Scratch(es), E - Replace 487,20



Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door trim F L, Bump(s), E - Replace	114,00
-------------------------------------	--------



Alloy rim R R, Scratch(es), Acceptable	0,00
--	------

