



TOYOTA Yaris: 1GHH729			
Vinnnumber:	<b>VNKKD3D360A067920</b>	Versionname:	<b>YARIS BER Hybrid Comfort 74PK Aut.</b>
First Registrationdate:	<b>7/02/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>37123</b>	Power Kw:	<b>55</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3413</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Luggage cover
Windows electric F	
Radio multimedia	
Type of headlighting:	<b>Headlighting Halogen</b>
Type of Lining:	<b>Lining fabrics</b>
Type of climate control:	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>NOT OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear			
Summer tyres:	<b>175/65/15/84 H Steel</b>		
	Fr.L.	Fr.R.	Dunlop: 6 mm
	Re.L.	Re.R.	Dunlop: 6 mm

Assistance equipment			
Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>

Total cost ex VAT	<b>244,44</b>
Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>0,00</b>



Wheel cover F R, Scratch(es), Acceptable	<b>0,00</b>
No pictures to display	
Seat cover F R, Stain, Cleaning	<b>25,00</b>



Seat cover R, Stain, Cleaning

25,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Seat cover F L, Stain, Cleaning

25,00



Wheel cover F L, Scratch(es), Acceptable

0,00

No pictures to display

Roof, Scratch(es), LI - Repair and paint (complete)

0,00



Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Front bumper, Scratch(es), Acceptable

0,00

No pictures to display