



BMW 3: 1FCX593

Vinnumber:	WBA3K11030F824340	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	28/05/2013	Fiscalpower:	
Expertise Mileage:	152937	Power Kw:	100
Bodytype:	Break	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1510
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear























	225/50/17/94 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Total cost ex VAT	2686,37
Door F R, Bump(s), LI - Repair and paint (complete)	318,35



Air vent R M, Damaged, E - Replace	204,00
------------------------------------	--------

		Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
		Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
		Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
		Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
		Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
		Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>			
		Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
		Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
		Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
		Backrest cover F R, Scratch(es), Smart repair	64,32
		Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80



Foglight L, Damaged, E - Replace

138,00

