



PEUGEOT Expert SWB: 1AFZ575

Vinnnumber:	VF3XS9HUCAZ066809	Versionname:	EXPERT B/F SWB L1H1 P.CD.Airco 90PK
First Registrationdate:	3/01/2011	Fiscalpower:	
Expertise Mileage:	184516	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2828
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/15/104 T Steel			
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	2634,31
-------------------	----------------

Interior, Dirty, Cleaning	100,00
---------------------------	---------------





Glove compartment lid, Damaged, E - Replace 228,00



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display

Rearlight L, Damaged, E - Replace 91,50



Trunk door R L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Scratch(es), LI - Repair and paint (complete) 232,88



Seat cover F L, Hole, E - Replace 300,00



Steering wheel, Worn, Acceptable 0,00



Rearlight L tailgate, Damaged, E - Replace 74,00



Roof, Rust, LI - Repair and paint (complete) 361,13



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Wing F L, Rust, LI - Repair and paint (complete) 165,13



Spare wheel compartment lining R R, Damaged, Smart repair 110,64



Door R R, Damaged, LI - Repair and paint (complete) 238,76



Ignition key, Missing, E - Replace 150,00

No pictures to display

Door moulding Lower F R, Unclapsed, N - Mount/Dismount 24,00



Trunk door R R, Bump(s) and scratch(es), It - Spot repair 115,56



