


PEUGEOT 5008: 1GPE112

Vinnnumber:	VF30A9HD8E5046081	Versionname:	5008 e-HDi Allure STT BMP 115PK Aut.
First Registrationdate:	24/03/2014	Fiscalpower:	
Expertise Mileage:	116409	Power Kw:	84
Bodytype:	MPV	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINNEN 200KM	Parking lot:	2504
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof
GPS storage	HD	Central consol F
GPS storage		Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/55/16/93 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	3556,84
-------------------	---------

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------





Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)

308,20



Interior, Dirty, Cleaning

50,00



Rearview mirror housing R, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Door panel R L, Scratch(es), Smart repair

110,64



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)

318,35



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Rocker panel inner F L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R R, Scratch(es), LI - Repair and paint (complete) 115,56



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Rear spoiler, Chemical pollution, LI - Repair and paint (complete) 115,56



Rocker panel inner R L, Bump(s), Acceptable 0,00


No pictures to display

Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35




Wing F R, Scratch(es), LI - Repair and paint (complete) 220,18





Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Roof, Bump(s) and scratch(es), LI - Repair and paint (complete) 481,50

