



VOLKSWAGEN Golf: YP5567

Vinnnumber:	WVWZZZAUZEP043827	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	23/01/2014	Fiscalpower:	
Expertise Mileage:	157061	Power Kw:	77
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1610
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 T Steel			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Uniroyal: 8 mm	Re.R.	Uniroyal: 8 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	1090,23
Front bumper, Unclasp(ed), N - Mount/Dismount	24,00



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------





Door R L, Bump(s), LI - Repair and paint (complete)	318,35
---	--------



Bonnet, Bump(s), LI - Repair and paint (complete)	386,08
---	--------

