



PEUGEOT Expert: 1FBE115

Vinnumber:	VF3XS9HM0DZ018798	Versionname:	EXPERT B/F SWB 227 L1H1 90PK
First Registrationdate:	14/05/2013	Fiscalpower:	
Expertise Mileage:	172898	Power Kw:	66
Bodytype:	Transporter	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV06
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD		Rear parking sensors	
Windows electric F			
Type of headlighting	Headlighting Halogen		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/65/15/102 T Steel			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1066,48
-------------------	---------

Sill outer R, Bump(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Damaged, Smart repair	110,64
-------------------------------------	--------



Sidwall RL (LCV), Bump(s) and scratch(es), It - Spot repair	115,56
---	--------



Door F R, Scratch(es), LI - Repair and paint (complete)	238,76
---	--------



Rearlight L, Damaged, E - Replace 91,50



Interior, Dirty, Cleaning 50,00



Bonnet, Bump(s), Acceptable 0,00

No pictures to display

Sliding door R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Windscreen, Repaired, Acceptable 0,00

No pictures to display

Door trim R R, Scratch(es), E - Replace 39,00



Seat cover F L, Deformed, Acceptable 0,00



Wing R R, Bump(s), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00

No pictures to display

Door trim F R, Scratch(es), E - Replace 39,00

