


MERCEDES A: 1GKI115

Vinnnumber:	WDD1760011V010941	Versionname:	A 200 CDI BE Style 136PK
First Registrationdate:	3/03/2014	Fiscalpower:	
Expertise Mileage:	184723	Power Kw:	100
Bodytype:		Body color:	Anthracite
Gearbox:	MAN 6 VIT	Rims summer:	Aluminium
Transmission:	Front	Oil level:	OK
Fueltype:	Diesel		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Seats electric F L
GPS storage	HD	Sun Roof electric
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining Alcantara	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK











Degree of wear

	225/40/18/92 Y LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1963,95
Bonnet, Stone chip(s), Acceptable			0,00
<i>No pictures to display</i>			
Front bumper, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Seat cover F L, Stain, Cleaning			25,00



	Alloy rim R R, Scratch(es), E - Replace	235,20
		
		
	Tailgate, Bump(s), Acceptable	0,00
<i>No pictures to display</i>		
	Alloy rim F L, Scratch(es), E - Replace	235,20
		
	Registration Document, Missing, E - Replace	150,00
		
	Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
		
		
	Certificate Of Conformity, Missing, E - Replace	150,00
		
	Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim F R, Scratch(es), E - Replace 235,20

