



SKODA Superb: 1EYH125

Vinnnumber:	TMBJJ73T6D9049348	Versionname:	SUPERB COMBI GreenLin.Ambition DPF 105PK
First Registrationdate:	19/04/2013	Fiscalpower:	77
Expertise Mileage:	160157	Power Kw:	77
Bodytype:	Break	Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2822
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Seats electric F L
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1659,96
-------------------	----------------

Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------




Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Roof, Bump(s), LI - Repair and paint (complete)	1057,80
---	---------



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door R L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Bonnet, Bad repair, Paint	0,00
---------------------------	------

