


**SKODA Superb: 1ESM066**

Vinnnumber:	<b>TMBJJ73T0D9043948</b>	Versionname:	<b>SUPERB COMBI GreenLin.Ambition DPF</b>
First Registrationdate:	<b>8/03/2013</b>	Fiscalpower:	<b>105PK</b>
Expertise Mileage:	<b>177152</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Blue</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>





















**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

**Total cost ex VAT** 695,77

**Bumper R, Bump(s), Acceptable** 0,00

**Tailgate, Bump(s), Acceptable** 0,00

		Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00	
		Bumper F L, Scratch(es), Acceptable	0,00	
			Bumper F R, Scratch(es), It - Spot repair	115,56
			Door R R, Bump(s), PDR - Knock out without painting	63,00
		Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00	
		Door R L, Bump(s), PDR - Knock out without painting	63,00	
		Wing R L, Scratch(es), Acceptable	0,00	
		Rear window, Scratch(es), E - Replace	0,00	
		Wing F L, Scratch(es), LI - Repair and paint (complete)	264,21	

