



VOLKSWAGEN GOLF VII: 1NNS993

Vinnumber:	VVWZZZAUZGW235501	Versionname:	1.6 TDI 66KW TRENDLINE
First Registrationdate:	29/03/2016	Fiscalpower:	
Expertise Mileage:	53266	Power Kw:	66
Bodytype:		Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	1532
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1773,50
-------------------	----------------

Tailgate, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Wheel cover R R, Scratch(es), E - Replace	30,00
---	--------------



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover F R, Scratch(es), E - Replace 30,00



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 454,50



Bodywork, Not original part, Remove lettering 0,00

No pictures to display

Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Seat cover R, Stain, Cleaning 25,00



Bumper R, Broken, Le - Replace and paint 651,00



Wing R L, Bump(s), LI - Repair and paint (complete) 308,20

