



VOLKSWAGEN Golf: 1HTC464

Vinnumber:	WVWZZZAUZFP540122	Versionname:	GOLF VAR Trendline 105PK
First Registrationdate:	25/09/2014	Fiscalpower:	
Expertise Mileage:	202915	Power Kw:	77
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance	OK		
Maintenance	OVER 13100 KM OF 242 DAGEN		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar removable
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Winter tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	875,24
-------------------	---------------

Door R R, Bump(s), Acceptable	0,00
-------------------------------	-------------



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	---------------



Wing R R, Bump(s), Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Tailgate, Bump(s), PDR - Knock out without painting 82,80



Ignition key, Missing, E - Replace 150,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00



Bumper F R, Scratch(es), It - Spot repair 115,56



Interior, Dirty, Cleaning 25,00

