



MAZDA CX-5: 1PLF872

| | | | |
|------------------------------------|--------------------------|--------------|-----------------------------------|
| Vinnnumber: | JMZKEF97600507832 | Versionname: | 2.0 SKYACTIV-G 163 SKYMOVE |
| First Registrationdate: | 2/08/2016 | Fiscalpower: | |
| Expertise Mileage: | 42998 | Power Kw: | 120 |
| Bodytype: | SUV | Body color: | Silver |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Petrol | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3610 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|-------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Luggage cover |
| Windows electric R | |
| Steering wheel multifunctional | |
| Type of headlighting: | Headlighting Halogen |
| Type of Lining: | Lining fabrics |
| Type of climate control: | Manual climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear


| | | | | |
|---------------|------------------------------|-----------------------|-------|-----------------------|
| | 225/65/17/106 H Steel | | | |
| Winter tyres: | Fr.L. | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
| | Re.L. | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

Total cost ex VAT 2402,10

Bonnet, Bad repair, LI - Repair and paint (complete) 348,09



Door panel R R, Damaged, E - Replace 132,00



Bumper R, Crack, Le - Replace and paint

766,80



Trunk lid covering R, Scratch(es), E - Replace

104,00



Ceiling, Damaged, E - Replace

564,00



Wing F L, Bad repair, LI - Repair and paint (complete)

264,21



Rocker panel inner F R, Bump(s), Acceptable


0,00

No pictures to display



Armrest F Mid, Damaged, E - Replace

198,00



Seat cover F R, Stain, Cleaning

25,00