



VOLO V40: 1GTU774

Vinnumber:	YV1MV8481E2155237	Versionname:	
First Registrationdate:	28/04/2014	Fiscalpower:	
Expertise Mileage:	143066	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3811
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Kleber: 6 mm	Re.R.	Kleber: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	961,42
Trunk lid covering R, Scratch(es), Acceptable	0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing R L, Bad repair, P - Check 0,00



Seat cover R L, Stain, Acceptable 0,00



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Wing F R, Bump(s), PDR - Knock out without painting 63,00



Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Door panel R R, Hole, Smart repair 110,64



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Mirror side blinker L, Crack, E - Replace 49,00

