



PEUGEOT 508: 1GRU401

Vinnnumber:	VF38D9HD8EL015627	Versionname:	BER e-HDI Access STT
First Registrationdate:	10/04/2014	Fiscalpower:	115PK
Expertise Mileage:	180819	Power Kw:	84
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4810
Maintenance	18700KM OF 10 MND		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	HD Luggage cover
GPS storage	
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Adaptive cruise control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H Steel			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 1817,23

Door panel R R, Scratch(es), E - Replace 114,00





Wheel cover F L, Scratch(es), E - Replace 30,00



Seat cover R, Stain, Cleaning 25,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover F R, Scratch(es), E - Replace 30,00



Bumper moulding F M, Broken, E - Replace 14,40



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Floor covering F L, Hole, E - Replace 252,00



Tailgate, Scratch(es), LI - Repair and paint (complete)

301,68



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Windscreen, Stone chip(s), P - Check

0,00

No pictures to display