


PEUGEOT 508: 1GMB939

Vinnnumber:	VF38URHC8EL003093	Versionname:	508 SW RXH BMP STT 163PK Aut.
First Registrationdate:	7/03/2014	Fiscalpower:	
Expertise Mileage:	115559	Power Kw:	120
Bodytype:		Body color:	White
Gearbox:	Automatic	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Hybrid Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3526
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Panoramic roof
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunctional		Rear parking sensors
Seats F heated		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Head-up Display		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/100 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Total cost ex VAT	2030,24
Mirror side blinker L, Scratch(es), E - Replace	30,00



Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68
---	--------



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F L polished, Damaged, E - Replace 235,20



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Scratch(es), LI - Repair and paint (complete) 290,08



Windscreen, Stone chip(s), E - Replace 487,20



Alloy rim R R polished, Rust, Acceptable 0,00



Bumper moulding R, Scratch(es), Smart repair 110,64



Door R R, Bump(s), PDR - Knock out without painting 63,00



Bumper moulding F, Scratch(es), Smart repair 110,64

