



CITROEN Jumper 35 LWB HR: 1EKD010

Vinnnumber:	VF7YCTMFC12282246	Versionname:	JUMPER 35 B/F LWB L3H2 Fresh(EU5)130PK
First Registrationdate:	3/01/2013	Fiscalpower:	
Expertise Mileage:	212528	Power Kw:	96
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	TRU13
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/70/15/109 S Steel			
Summer tyres:	Fr.L.	Uniroyal: 9 mm	Fr.R.	Uniroyal: 9 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 2572,11

Sliding door panel R, Broken, E - Replace 59,00



Sidewall FL (LCV), Bump(s) and scratch(es), It - Spot repair 115,56



Seat cover F L, Stain, Cleaning 25,00



Trunk door R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wiper Blade R, Rust, Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Sill outer R, Rust, LI - Repair and paint (complete)	232,88



Rocker panel inner F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk door R R, Strained , I - Repair	0,00



Door seal R, Damaged, E - Replace	50,00
-----------------------------------	-------



Sidewall RL (LCV), Bump(s) and scratch(es), It - Spot repair	115,56
--	--------



Bumper corner R L, Strained , Smart repair	110,64
--	--------



Wing F L, Damaged, Le - Replace and paint	427,51
---	--------



Bumper F L, Scratch(es), Smart repair	110,64
---------------------------------------	--------



Internal Boot Lining L, Broken, E - Replace	35,00
---	-------



Trunk door R L, Bump(s) and scratch(es), E - Replace 346,00



Bumper grille, Missing, E - Replace 30,30



Wing trim R L, Broken, E - Replace 69,00



Headlight protector F L, Broken, E - Replace 45,00



Engine protective plate, Hole, E - Replace 45,00



Sidewall mid R (LCV), Scratch(es), LI - Repair and paint (complete) 200,00



Rearview mirror R complete, Damaged, E - Replace 138,00



Rearview mirror housing L, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door panel R, Damaged, E - Replace 35,00



Wiper Blade L, Rust, Acceptable	0,00
<i>No pictures to display</i>	
Sliding door R, Scratch(es), LI - Repair and paint (complete)	382,02

