



IVECO Daily 40C15: 1BWV798

Vinnnumber:	ZCFC40A4205806431	Versionname:	DAILY CH2C 40C15 146PK
First Registrationdate:	14/06/2010	Fiscalpower:	3500KG
Expertise Mileage:	162890	Power Kw:	107
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	LCV26
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Type of Tow bar Tow bar fixed
Type of headlighting Headlighting Halogen	
Type of Lining Lining fabrics	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/75/16/107 R Steel			
Summer tyres:	Fr.L.	Firestone: 8,5 mm	Fr.R.	Firestone: 8,5 mm
	Re.L.	Firestone: 4 mm	Re.R.	Firestone: 4 mm

Assistance equipment

Total cost ex VAT	3235,63
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel R R, Damaged, E - Replace	91,50



Cupholder, Missing, E - Replace	25,00
---------------------------------	-------



Windscreen, Stone chip(s), Windscreen repair	58,80
----------------------------------------------	-------



Roof pillar R, Bump(s), Acceptable 0,00

No pictures to display

Floor covering F L, Damaged, E - Replace 237,00



Interior, Dirty, Cleaning 25,00



Bumper R, Bump(s), E - Replace 329,40



De-icer nozzle internal R, Missing, E - Replace 153,00



Console storage compartment, Damaged, P - Check 0,00



Sill outer L, Bump(s), It - Spot repair 115,56



Boot carpet, Hole, E - Replace 75,00



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Door R R, Damaged, Le - Replace and paint 746,18



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	165,13
---------------------------------------------------------------------	--------



Steering column top cover, Not functioning (well), E - Replace	15,00
----------------------------------------------------------------	-------



Cupholder, Missing, E - Replace	25,00
---------------------------------	-------



Rearview mirror housing R, Damaged, E - Replace	35,00
-------------------------------------------------	-------



Ceiling, Strained , P - Check	0,00
-------------------------------	------



Instruction book, Missing, E - Replace	0,00
----------------------------------------	------

No pictures to display

Phone/Car Kit, Incomplete, E - Replace	150,00
----------------------------------------	--------



Inner door handle R R, Not functioning (well), E - Replace	33,00
------------------------------------------------------------	-------



Armrest R, Not functioning (well), P - Check	0,00
----------------------------------------------	------



Door panel R R, Strained , E - Replace	91,50
----------------------------------------	-------



De-icer nozzle internal L, Missing, E - Replace 153,00



Bonnet, Bump(s), LI - Repair and paint (complete) 217,56



Mirror side blinker R, Crack, E - Replace 28,50



Door panel R R, Missing, E - Replace 39,00



Seat cover F L, Tear, E - Replace 300,00



Dashboard, Hole, Acceptable 0,00



Door moulding Lower F L, Missing, E - Replace 91,50



Door R L, Crack, E - Replace 35,00

