



VOLKSWAGEN Golf: 1DLV490

Vinnumber:	WVWZZZ1KZDW015991	Versionname:	GOLF BER BlueMotion DPF
First Registrationdate:	19/06/2012	Fiscalpower:	105PK
Expertise Mileage:	185386	Power Kw:	77
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3331
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
GPS storage	CD Luggage cover
GPS storage	
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/98 H LightMetal			
Summer tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 3 mm	Re.R.	Goodyear: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	769,38
-------------------	--------

Rear window, Scratch(es), E - Replace	0,00
---------------------------------------	------



Wing R R, Scratch(es), LI - Repair and paint (complete)	0,00
---	------



Wing F L, Bump(s), LI - Repair and paint (complete)	220,18
---	--------



Sill outer R, Bad repair, Acceptable 0,00



Tailgate, Bump(s), LI - Repair and paint (complete) 0,00



Foglight R, Broken, E - Replace 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Sill outer L, Bump(s), LI - Repair and paint (complete) 0,00



Rearview mirror housing R, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Damaged, LI - Repair and paint (complete) 235,80



Ashtray R, Damaged, E - Replace 59,60



Grill, Damaged, E - Replace 42,00



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display