



VOLKSWAGEN TOURAN: 1GW681

Vinnumber:	WVGZZ1TZEW097585	Versionname:	
First Registrationdate:	20/06/2014	Fiscalpower:	
Expertise Mileage:	64143	Power Kw:	77
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2322
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Panoramic roof
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment





















Total cost ex VAT	1273,24
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	--------------



Foglight R, Damaged, E - Replace	138,00
----------------------------------	---------------

		
Bumper grille, Damaged, E - Replace		59,00
		
Wing R L, Bump(s), PDR - Knock out without painting		63,00
		
Door F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door trim R L, Damaged, E - Replace		114,00
		
Tailgate, Bump(s), PDR - Knock out without painting		82,80
		
		
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)		95,00
		
Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)		95,00
		
Rearview mirror housing R, Scratch(es), Smart repair		110,64
		
Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)		211,80
		
Door trim F L, Damaged, E - Replace		114,00



Rear window, Scratch(es), Acceptable

0,00

No pictures to display