



VOLKSWAGEN Touran: 1FBT905

Vinnnumber:	WVGZZZ1TZDW067789	Versionname:	TOURAN Trendline BMT Start/Stop 105PK
First Registrationdate:	17/05/2013	Fiscalpower:	
Expertise Mileage:	146239	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4221
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1003,33
--------------------------	----------------

Alloy rim R L polished, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
--	---------------





Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Spare wheel compartment lining, Incomplete, E - Replace 15,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 366,35



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Door F L, Scratch(es), Acceptable 0,00

No pictures to display