



TOYOTA Auris: 1HLG263

Vinnnumber:	SB1MS3JE00E104471	Versionname:	AURIS BER HSD
First Registrationdate:	19/08/2014		Hybr.Premium CVT 99PK
Expertise Mileage:	83294	Fiscalpower:	Aut.
Bodytype:	Break	Power Kw:	73
Gearbox:	Automatic	Body color	Blue
Transmission:	Front	Paint type	Metalic
Fueltype:	Hybrid Petrol	Rims summer	Aluminium
Maintenance	OK	Oil level	OK
Battery functioning	Yes	Parking lot	1410
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Panoramic roof
GPS storage	Central consol F
GPS storage HD	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting Headlighting LED	
Type of GPS GPS big screen color	
Type of Lining Lining semi-artificial leather	
Type of climate control Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 W LightMetal			
Summer tyres:	Fr.L.	Dunlop: 5 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	300,64
-------------------	--------

Wing F R, Stone chip(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------





Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bonnet, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Smart repair	110,64



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

