


SKODA Superb: 1GXCS93

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber: | TMBJE73T7E9055195 | Versionname: | SUPERB COMBI Elegance |
| First Registrationdate: | 23/05/2014 | Fiscalpower: | DSG 140PK Aut. |
| Expertise Mileage: | 51181 | Power Kw: | 103 |
| Bodytype: | Break | Body color: | Black |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3620 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|---|-----------------------|
| Radio CD | Seats electric R |
| Windows electric F | Seats electric F L |
| Windows electric R | Seats electric F R |
| Cruise Control | Central consol F |
| Steering wheel multifunctional | Luggage cover |
| Seats F heated | Front parking sensors |
| Radio multimedia | Rear parking sensors |
| Type of headlighting: Headlighting Halogen | |
| Type of GPS: GPS big screen color | |
| Type of Lining: Lining leather | |
| Type of climate control: Autom climate control | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|--------------------------|-------|--------------------------|
| 225/45/17/91 V LightMetal | | | | |
| Summer tyres: | Fr.L. | Continental: 4 mm | Fr.R. | Continental: 4 mm |
| | Re.L. | Continental: 5 mm | Re.R. | Continental: 5 mm |

Assistance equipment

| | |
|--|--------|
| Total cost ex VAT | 647,02 |
| Wing R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |



| | |
|--|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|



| | |
|------------------------------|------|
| Bonnet, Repaired, Acceptable | 0,00 |
|------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Bumper R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|---|--------|
| Tailgate, Bump(s), LI - Repair and paint (complete) | 362,02 |
|---|--------|



| | |
|--|-------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--|-------|

