


MERCEDES A: YP5480

Vinnumber:	WDD1760121J204617	Versionname:	A 180 CDI BE 109PK
First Registrationdate:	26/11/2013	Fiscalpower:	
Expertise Mileage:	80761	Power Kw:	80
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2325
Number of doors:	5		
Number of seats:	5		
Number head rests:	1		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunction		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather and alcantara	
Type of climate control	Manual climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/94 V LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 0,1 mm	Fr.R.	Bridgestone: 0,1 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment

Spare wheel	No	Jack	No
Emergency spare wheel	No		
Repair kit	No		

Total cost ex VAT 928,53

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00

Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00




Bumper F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Stone chip(s), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Tyre repair kit, Missing, E - Replace	210,53
---------------------------------------	--------



Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	--------



Bonnet, Bump(s), PDR - Knock out without painting	63,00
---	-------

