



MERCEDES Vito: 1ALY241			
Vinnnumber:	WDF63960113624108	Versionname:	VITO 113 B/F SWB CU+ 250kg 136PK
First Registrationdate:	7/02/2011	Fiscalpower:	
Expertise Mileage:	164061	Power Kw:	100
Bodytype:	Transporter	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2705
Number of doors:	4		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options		
Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining artificial leather	
Type of climate control	Manual climate control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	NOT OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/65/16/107 T Steel			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment	
Spare wheel	Yes Jack Yes
Total cost ex VAT	835,06
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Inner seat cover L, Missing, E - Replace	15,00



Tailgate, Bump(s), LI - Repair and paint (complete)	362,02
---	--------





Bumper R, Deformed, E - Replace	329,40
---------------------------------	--------



Bonnet, Bump(s), Acceptable	0,00
-----------------------------	------

No pictures to display

Ceiling, Burned, Smart repair	64,32
-------------------------------	-------



Bodywork, Not original part, Remove lettering	0,00
---	------

No pictures to display

Wing F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F L, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Seat cover F R, Burned, Smart repair	64,32
--------------------------------------	-------

