


BMW 1: EU8845

Vinnnumber:	WBA1B51010J842783	Versionname:	1 BER HATCH 120dX 184PK
First Registrationdate:	10/06/2013	Fiscalpower:	
Expertise Mileage:	166118	Power Kw:	135
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	4 Weel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3830
Maintenance	6000 KM 12:2018		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Seats electric F R
GPS storage		Sun Roof electric
Windows electric F		Central consol F
Windows electric R		Luggage cover
Cruise Control		Front parking sensors
Steering wheel multifunction		Rear parking sensors
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 V LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 8 mm	Re.R.	Bridgestone: 8 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	2061,35
-------------------	----------------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Wing R L, Bump(s), PDR - Knock out without painting

63,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Windscreen, Stone chip(s), E - Replace 487,20



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Xenon headlight L, Scratch(es), E - Replace 696,00

