



SKODA Octavia: 1ELB261			
Vinnnumber:	<b>TMBHT21Z0D2107045</b>	Versionname:	<b>OCTAVIA COMBI GTec Ambition DPF 105PK</b>
First Registrationdate:	<b>10/01/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>167801</b>	Power Kw:	<b>77</b>
Bodytype:		Body color	<b>Blue</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>2327</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		

Options			
Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>195/65/15/91 T LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>588,56</b>
Wing R R, Scratch(es), Acceptable			<b>0,00</b>



Rocker panel inner R L, Scratch(es), Acceptable	<b>0,00</b>
---	-------------



Wing F R, Scratch(es), Acceptable 0,00



Door trim R L, Scratch(es), E - Replace 114,00



Door R L, Bump(s) and scratch(es), Acceptable 0,00



Wing R L, Scratch(es), Acceptable 0,00



Ignition key, Missing, E - Replace 150,00



Door trim R R, Scratch(es), E - Replace 114,00



Bumper R, Scratch(es), Acceptable 0,00



Bumper F R, Scratch(es), It - Spot repair 115,56





Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Bump(s) and scratch(es), Acceptable 0,00

