



**FIAT Ducato 35 MWB HR: 1EUE173**

Vinnumber:	<b>ZFA25000002321594</b>	Versionname:	<b>DUCATO 35 B/F MWB HR (EU5) 130PK</b>
First Registrationdate:	<b>21/03/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>160419</b>	Power Kw:	<b>96</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Yellow</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV03</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>	Type of Tow bar	<b>Tow bar fixed</b>
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>NOT OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>NOT OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/70/15/109 S Steel</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 8 mm</b>	Fr.R.	<b>Pirelli: 8 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Total cost ex VAT	2893,06
Trunk door R L, Bump(s) and scratch(es), It - Spot repair	115,56



Trunk door panel R, Damaged, E - Replace	50,00
--	-------



Trunk door R R, Damaged, Le - Replace and paint 396,00



Interior, Dirty, Cleaning 0,00



Ignition key, Missing, E - Replace 150,00

No pictures to display

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Internal Boot Lining L, Damaged, Smart repair 110,64



Door trim R R, Missing, E - Replace 91,50



Windscreen, Stone chip(s), Acceptable 0,00

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Door trim R R, Missing, E - Replace 91,50



Rearview mirror L complete, Damaged, E - Replace 138,00



Trunk door panel L, Damaged, E - Replace 50,00



Bumper R, Scratch(es), Smart repair 110,64



Internal Boot Lining R, Damaged, Smart repair 110,64



Door F L, Scratch(es), LI - Repair and paint (complete) 238,76



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Seat cover F L, Damaged, E - Replace 300,00

