



**VOLKSWAGEN Crafter 35 MWB hoog dak: 440BTG**

Vinnumber:	<b>WV1ZZZ2EZA6011286</b>	Versionname:	<b>CRAFTER 35 B/F MWB HR</b>
First Registrationdate:	<b>9/06/2010</b>	Fiscalpower:	<b>88pk</b>
Expertise Mileage:	<b>190583</b>	Power Kw:	<b>65</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>Red</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV05</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD	
Windows electric F	
Type of headlighting	<b>Headlighting Halogen</b>
Type of Lining	<b>Lining fabrics</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>235/65/16/115 R Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

**Assistance equipment**

Total cost ex VAT	2750,60
Trunk door R R, Bump(s) and scratch(es), It - Spot repair	115,56



Wing F R, Scratch(es), LI - Repair and paint (complete)	165,13
---	--------



Sill outer R, Scratch(es), LI - Repair and paint (complete)	232,88
---	--------



Trunk door panel R, Damaged, E - Replace 50,00



Glove compartment lid, Damaged, E - Replace 228,00



Spare wheel compartment lining R L, Bump(s), Smart repair 110,64



Bumper R, Damaged, E - Replace 329,40



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Trunk door panel L, Damaged, E - Replace 50,00



Door R L, Bump(s), PDR - Knock out without painting 181,80



Trunk door R L, Damaged, Le - Replace and paint 446,00



Spare wheel compartment lining R R, Bump(s), Smart repair 110,64



Bumper F R, Scratch(es), Smart repair 110,64



Ignition key, Missing, E - Replace 150,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76

