



DACIA Lodgy: 1EEE119			
Vinnnumber:	UU1JSDBC647945719	Versionname:	LODGY LauREate 7pl. 107PK
First Registrationdate:	6/11/2012	Fiscalpower:	
Expertise Mileage:	126928	Power Kw:	79
Bodytype:	Hatchback	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3624
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		


Options	
Windows electric F	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes

Total cost ex VAT	2336,80
Wheel covers (all), Not original part, E - Replace	96,00



Internal Boot Lining R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Trunk lid covering R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	

Roof, Bump(s) and scratch(es), LI - Repair and paint (complete) 385,20

No pictures to display

Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,68



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 246,56



Door R L, Scratch(es), LI - Repair and paint (complete) 254,68



Internal Boot Lining L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Damaged, Le - Replace and paint 607,20



Roof, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 169,44



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 169,44



Ceiling, Deformed, Acceptable	0,00
<i>No pictures to display</i>	
Wing R R, Bad repair, Acceptable	0,00



De-icer nozzle internal L, Damaged, E - Replace	153,60
---	--------

