



MERCEDES CLA SHOOTING BRAKE: 1NAU447

Vinnumber:	WDD1179121N329418	Versionname:	1.5 CLA 180 D URBAN SHOOTING BRAKE
First Registrationdate:	7/01/2016	Fiscalpower:	
Expertise Mileage:	167666	Power Kw:	80
Bodytype:		Body color	Silver
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	SERV A IN 20900 KM	Parking lot	1204
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/40/18/92 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 5,5 mm	Fr.R.	Michelin: 5,5 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2477,94
-------------------	----------------

Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	---------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Alloy rim F R, Damaged, E - Replace 235,20



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Damaged, Le - Replace and paint 651,00



Front bumper, Tear, Smart repair 110,64



Door frame R L, Bump(s), It - Spot repair 115,56



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Stone chip(s), Windscreen repair 0,00



Trunk lid covering R, Damaged, Smart repair 110,64



Interior, Dirty, Acceptable 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Luggage space cover, Strained , E - Replace 25,00



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35

