


**RENAULT Master 35 L2H2: 1CFS446**

Vinnnumber:	<b>VF1MAFEEC45882179</b>	Versionname:	<b>MASTER 35 B/F L2H2 Gr.Conf.145PK</b>
First Registrationdate:	<b>15/11/2011</b>	Fiscalpower:	
Expertise Mileage:	<b>78955</b>	Power Kw:	<b>107</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>NOT OK</b>	Parking lot:	<b>LCV11</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD		Central consol F	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of Lining	<b>Lining artificial leather</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>NOT OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/65/16/112 R Steel</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 1,5 mm</b>	Fr.R.	<b>Bridgestone: 1,5 mm</b>
	Re.L.	<b>Bridgestone: 0,5 mm</b>	Re.R.	<b>Bridgestone: 0,5 mm</b>

**Assistance equipment**

Spare wheel	<b>No</b>	Jack	<b>No</b>
-------------	-----------	------	-----------

Total cost ex VAT	3333,07
-------------------	---------

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

*No pictures to display*

Trunk door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	200,00
---------------------------------------------------------------------------	--------



Jack, Missing, E - Replace	42,00
----------------------------	-------

*No pictures to display*

Rearview mirror housing R, Missing, E - Replace	120,00
-------------------------------------------------	--------



Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 165,13



Inner door handle F L, Missing, E - Replace 33,00



Instruction book, Missing, E - Replace 0,00

No pictures to display

Door moulding Lower F L, Scratch(es), E - Replace 91,50



Wing trim R R, Missing, E - Replace 69,00



Boot cover, Damaged, Repair/replace (lump sum) 0,00



Sidewall panel FL, Strained , Repair/replace (lump sum) 0,00



Bumper R, Scratch(es), E - Replace 329,40



Rearlight R , Damaged, E - Replace 91,50



Sidewall RL (LCV), Bump(s) and scratch(es), LI - Repair and paint (complete) 200,00



Sidewall FL (LCV), Bump(s) and scratch(es), LI - Repair and paint 200,00

(complete) 200,00



Door moulding Lower F R, Missing, E - Replace 91,50



Registration Document, Missing, E - Replace 150,00

No pictures to display

Brand badge R, Missing, E - Replace 15,00



Sliding door R, Bump(s), PDR - Knock out without painting 102,60



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 327,15



De-icer nozzle internal L, Missing, E - Replace 153,00



Maintenance, Maintenance, Execute 0,00



Front bumper, Damaged, E - Replace 398,40



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)

238,76



Wing F R, Scratch(es), LI - Repair and paint (complete)

165,13

