



DACIA Dokker: 1EYG757			
Vinnumber:	UU10SDCL548611633	Versionname:	DOKKER Laur?ate 90PK
First Registrationdate:	19/04/2013	Fiscalpower:	
Expertise Mileage:	189493	Power Kw:	66
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4116
Battery functioning:	Yes		
Number of doors:	6		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options			
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Alarm			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		










Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment	
Spare wheel	Yes Jack Yes
Total cost ex VAT	2427,30
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wheel cover R R, Scratch(es), E - Replace	24,00



Aerial Damaged, E - Replace	12,00
-----------------------------	--------------

	Actual, Damaged, E - Replace	12,00
Wheel cover F L, Scratch(es), Acceptable 0,00		
<i>No pictures to display</i>		
Door F R, Scratch(es), LI - Repair and paint (complete)		254,68
		
		
Bonnet, Scratch(es), LI - Repair and paint (complete)		232,06
		
Ignition key, Missing, E - Replace		150,00
<i>No pictures to display</i>		
Door R R, Scratch(es), LI - Repair and paint (complete)		254,68
		
Door panel R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door frame F L, Bump(s) and scratch(es), It - Spot repair		115,56
		
Trunk door R L, Bump(s), PDR - Knock out without painting		82,80
		
Wheel cover R L, Damaged, E - Replace		24,00
		
		
Luggage space cover, Damaged, E - Replace		192,00



Wheel cover F R, Damaged, E - Replace 24,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete) 248,40



Trunk door R R, Bump(s), Acceptable 0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Headlight L, Damaged, E - Replace 336,00



Roof pillar L, Bump(s), Acceptable 0,00

No pictures to display

Headlight R, Damaged, E - Replace 246,00

