



<b>VOLKSWAGEN Touran: 1HYY509</b>			
Vinnnumber:	<b>WVGZZZ1TZFW026792</b>	Versionname:	<b>TOURAN Trendline BMT St/St 7pl/DSG 105PK</b>
First Registrationdate:	<b>3/11/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>93793</b>	Power Kw:	<b>77</b>
Bodytype:	<b>MPV</b>	Body color:	<b>Dark Blue</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4624</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>7</b>		
Number head rests:	<b>7</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

<b>Options</b>			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	<b>Tow bar removable</b>
Seats F heated			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

<b>Assistance equipment</b>	
Total cost ex VAT	618,98
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00



Alloy rim R L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display	
Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	220,48

Wing F R, Dimp(s) and scratch(es), LI - Repair and paint (complete) 220,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Interior, Dirty, Cleaning 0,00



Windscreen, Stone chip(s), Windscreen repair 58,80



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00

No pictures to display