



KIA Cee'd: BU5971			
Vinnnumber:	USYHN816AEL056074	Versionname:	CEE'D SW Sense ISG EcoDyn.128PK
First Registrationdate:	16/07/2013	Fiscalpower:	
Expertise Mileage:	94043	Power Kw:	94
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2322
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Seats electric F L
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/5/16/91 H LightMetal			
	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Michelin: 8 mm	Re.R.	Michelin: 8 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes

Total cost ex VAT	2147,51
Wing R R, Damaged, LI - Repair and paint (complete)	308,20



Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete)	310,50
---	--------






Bumper F L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Ignition key, Missing, E - Replace 150,00

No pictures to display