



TOYOTA AURIS TOURING SPORTS: 1NGT633				
Vinnnumber:	SB1ZS3JE20E228909	Versionname:	1.8 HYBRID LOUNGE CVT	
First Registrationdate:	22/02/2016	Fiscalpower:	AUTO	
Expertise Mileage:	47600	Power Kw:	100	
Bodytype:		Body color	Grey	
Gearbox:	Automatic	Paint type	Metalic	
Transmission:	Front	Rims summer	Aluminium	
Fueltype:	Hybrid Petrol	Oil level	OK	
Battery functioning	Yes	Parking lot	3330	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
GPS storage	HD	Luggage cover		
GPS storage		Front parking sensors		
Windows electric F		Rear parking sensors		
Windows electric R				
Cruise Control				
Steering wheel multifunctional				
Seats F heated				
Radio multimedia				
Type of headlighting	Headlighting Xenon			
Type of GPS	GPS big screen color			
Type of Lining	Lining semi-leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	225/45/17/91 W LightMetal			
	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			441,39	
Mirror side blinker R, Scratch(es), Acceptable			0,00	
No pictures to display				
Wing R R, Bump(s), Acceptable			0,00	
No pictures to display				
Alloy rim F R polished, Scratch(es), Acceptable			0,00	
No pictures to display				
Grill, Damaged, E - Replace			79,40	



Wing F R, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim R R polished, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Scratch(es), 67 - Polish 55,19



Alloy rim F L polished, Damaged, LI - Repair and paint (complete) 95,00



Front bumper, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

