



BMW 2 ACTIVE TOURER: SJ5759

Vinnnumber:	WBA2C11020V519068	Versionname:	2.0 218D (110KW) ACTIVE TOURER
First Registrationdate:	9/07/2015	Fiscalpower:	
Expertise Mileage:	56484	Power Kw:	110
Bodytype:		Body color:	Beige
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2123
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Windows electric F		Seats electric F L	
Windows electric R		Seats electric F R	
Cruise Control		Central consol F	
Steering wheel multifunction		Luggage cover	
Radio multimedia		Front parking sensors	
Type of headlighting	Headlighting LED	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Continental: 7 mm	Fr.R.	Continental: 7 mm
	Re.L.	Continental: 8 mm	Re.R.	Continental: 8 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	682,55
-------------------	---------------

Foglight L, Deformed, E - Replace	138,00
-----------------------------------	---------------



Bumper moulding R Mid, Damaged, E - Replace	14,40
---------------------------------------------	--------------



Alloy rim F R, Scratch(es), Acceptable	0,00
----------------------------------------	-------------

No pictures to display

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35

