


PEUGEOT 508: 1FJY365

Vinnnumber:	VF38E9HL0DL036588	Versionname:	508 SW Active 115PK
First Registrationdate:	22/07/2013	Fiscalpower:	
Expertise Mileage:	175555	Power Kw:	84
Bodytype:	Break	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2825
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	No Tow bar
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1703,38
Ignition key, Missing, E - Replace	0,00
<i>No pictures to display</i>	
Alloy rim F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Protection plate M, Tear, E - Replace	74,00



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

no pictures to display

Luggage space cover, Damaged, E - Replace 240,00



Wing R R, Bump(s), LI - Repair and paint (complete) 308,20



Alloy rim R R, Damaged, LI - Repair and paint (complete) 95,00




Bumper R, Bump(s) and scratch(es), Le - Replace and paint 651,00



Bumper R, Bump(s) and scratch(es), Le - Replace and paint 651,00



Bumper R, Bump(s) and scratch(es), Le - Replace and paint 651,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Reflector, Damaged, E - Replace 20,00



Alloy rim F R, Damaged, LI - Repair and paint (complete) 95,00

