


PEUGEOT 308: 1EXC195

Vinnnumber:	VF34C9HP0DS054199	Versionname:	308 BER Access 92PK
First Registrationdate:	11/04/2013	Fiscalpower:	
Expertise Mileage:	150764	Power Kw:	68
Bodytype:		Body color	Silver
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1205
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	
Sport seats		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V Steel				
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 2 mm	Re.R.	Michelin: 2 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	748,00
-------------------	--------

Wheel cover F R, Broken, E - Replace	30,00
--------------------------------------	-------



Door trim F L, Stone chip(s), Acceptable	0,00
--	------

No pictures to display

Door trim F R, Stone chip(s), Acceptable	0,00
--	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover R R, Scratch(es), E - Replace	0,00
---	------



Door trim R L, Stone chip(s), Acceptable 0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 428,20



Wheel cover F L, Scratch(es), E - Replace 30,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 259,80



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display

Rocker panel inner R L, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 0,00