



## PEUGEOT Expert: 1CUK462

Vinnnumber:	<b>VF3XU9HM0CZ003874</b>	Versionname:	<b>EXPERT B/F MWB 229 L2H1 FAP(EU5)90PK</b>
First Registrationdate:	<b>1/03/2012</b>	Fiscalpower:	
Expertise Mileage:	<b>156502</b>	Power Kw:	<b>66</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4633</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	<b>Tow bar fixed</b>
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>No GPS</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>215/60/16/103 T Steel</b>			
Summer tyres:	Fr.L.	<b>Fulda: 5 mm</b>	Fr.R.	<b>Fulda: 5 mm</b>
	Re.L.	<b>Fulda: 4 mm</b>	Re.R.	<b>Fulda: 4 mm</b>

## Assistance equipment

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	328,56
-------------------	--------

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Sliding door R, Dent(s), PDR - Knock out without painting	63,00
---	-------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bodywork, Not original part, Acceptable	0,00
---	------

No pictures to display

Ignition key, Missing, E - Replace	150,00
------------------------------------	--------

No pictures to display

Sidewall RL (LCV), Dent(s), It - Spot repair	115,56
--	--------



Sliding door L, Bad repair, Acceptable 0,00

