



PEUGEOT 308 SW: 1KTK620

Vinnnumber:	VF3LCBHYBFS169194	Versionname:	1.6 BLUEHDI 73KW S/S ACTIVE
First Registrationdate:	30/06/2015	Fiscalpower:	
Expertise Mileage:	201672	Power Kw:	73
Bodytype:		Body color	Dark Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	IN 9800 KM	Parking lot	1230
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	
Level control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	4438,99
--------------------------	----------------

Seat cover F R, Burned, E - Replace	312,00
--	---------------



Spoiler R, Scratch(es), E - Replace	176,63
--	---------------



Door R L, Scratch(es), LI - Repair and paint (complete) 254,68



Wing R R, Dent(s), LI - Repair and paint (complete) 294,56



Wing R L, Scratch(es), LI - Repair and paint (complete) 246,56



Floor covering F L, Hole, E - Replace 240,00



Roof pillar L, Dent(s), Acceptable 0,00



Bumper R, Broken, Le - Replace and paint 535,20



Bonnet, Stone chip(s), Acceptable 0,00



Full screen GPS, Broken, E - Replace 236,48



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 350,68



Front bumper, Scratch(es), LI - Repair and paint (complete) 169,44



Covering interior front pillar L, Burned, E - Replace 99,12



Ceiling, Burned, E - Replace 424,00



Seat cover F L, Burned, E - Replace 312,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 398,68



Seat cover R R, Stain, Cleaning 25,00



Sill (outer), Scratch(es), LI - Repair and paint (complete) 248,40

Slit outer L, Scratch(es), Lt - Repair and paint (complete)

240,90



Central pillar R, Dent(s) and scratch(es), It - Spot repair

115,56

