



CITROEN JUMPER: 1KPA038			
Vinnnumber:	<b>VF7YCTMFC12799035</b>	Versionname:	<b>2.2 HDI 96KW 35 L3H2 BUSINESS</b>
First Registrationdate:	<b>5/06/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>83092</b>	Power Kw:	<b>96</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>LCV11</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options			
Radio CD		Central consol F	
GPS storage	<b>HD</b>	Rear parking sensors	
GPS storage		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>215/70/15/109 S Steel</b>			
Summer tyres:	Fr.L.	<b>Toyo: 5 mm</b>	Fr.R.	<b>Toyo: 5 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>1474,16</b>
Trunk door panel L, Crack, E - Replace			<b>50,00</b>



Sidewall FL (LCV), Dent(s), PDR - Knock out without painting	<b>175,00</b>
<i>No pictures to display</i>	
Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>382,02</b>



Trunk door panel R, Crack, E - Replace 50,00



Internal Boot Lining L, Broken, E - Replace 50,00




Rocker panel inner F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Trunk door R L, Dent(s), Acceptable 0,00

*No pictures to display*

Sidewall RR (LCV), Dent(s) and scratch(es), LI - Repair and paint (complete) 544,00



Door F R, Scratch(es), Acceptable 0,00

*No pictures to display*

Sunblind L, Crack, E - Replace 112,50



Bumper F L, Scratch(es), Smart repair 110,64

