



PEUGEOT 5008: 1GFP114

Vinnumber:	VF30A9HD8ES008234	Versionname:	5008 Allure 115PK
First Registrationdate:	27/01/2014	Fiscalpower:	
Expertise Mileage:	111755	Power Kw:	84
Bodytype:	SUV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3426
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Panoramic roof	
Windows electric F	Central consol F	
Windows electric R	Luggage cover	
Cruise Control	Front parking sensors	
Seats F heated	Rear parking sensors	
Radio multimedia	Type of Tow bar	No Tow bar
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Head-up Display		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/50/1/95 W LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Compressor **Yes**

Total cost ex VAT **2021,88**

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) **308,20**



Bumper R, Scratch(es), LI - Repair and paint (complete) **211,80**



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Protection plate M, Tear, E - Replace 74,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00





Rear spoiler, Scratch(es), LI - Repair and paint (complete) 115,56



Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 301,68



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Headlight protector F L, Scratch(es), Smart repair 110,64



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00

