



BMW X1: 1FJG077			
Vinnumber:	WBAVY11050VW89388	Versionname:	X1 sDrive16 116PK
First Registrationdate:	15/07/2013	Fiscalpower:	
Expertise Mileage:	53115	Power Kw:	85
Bodytype:	Hatchback	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3724
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Seats F heated	Tow bar removable
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control













Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/50/17/94 H Steel			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment	
Total cost ex VAT	1630,46
Wheel cover R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Luggage space cover, Missing, E - Replace	240,00



Wheel cover F R, Scratch(es), E - Replace	30,00
<i>No pictures to display</i>	
Rear spoiler, Bad repair, Acceptable	0,00

		Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20	
			Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>				
		Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35	
			Sill outer L, Scratch(es), It - Spot repair	115,56
		Door R R, Scratch(es), LI - Repair and paint (complete)		318,35
		Ignition key, Missing, E - Replace		150,00
<i>No pictures to display</i>				
		Certificate Of Conformity, Missing, E - Replace	150,00	
<i>No pictures to display</i>				