



MERCEDES Sprinter 300: 1EXR505

Vinnnumber:	WDB90663515787572	Versionname:	SPRINTER B/F 313 3500kg LWB HR 129PK
First Registrationdate:	16/04/2013	Fiscalpower:	
Expertise Mileage:	255932	Power Kw:	95
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV16
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	Type of Tow bar	No Tow bar
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/65/16/113 R Steel			
Summer tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	772,35
-------------------	---------------

Bumper R, Deformed / Strained, E - Replace	222,00
--------------------------------------------	---------------



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	231,15
---------------------------------------------------------------------	---------------



Sliding door R, Scratch(es), Acceptable	0,00
-----------------------------------------	-------------

No pictures to display

Rearview mirror glass R, Broken, E - Replace	13,50
----------------------------------------------	--------------



Seat cover F L, Worn, Acceptable 0,00



Brand badge R, Missing, E - Replace 25,00



Bonnet, Dent(s), Acceptable 0,00

No pictures to display

Roof pillar R, Dent(s) and scratch(es), LI - Repair and paint (complete) 165,14



Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door R R, Dent(s), It - Spot repair 115,56



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Not original part, Acceptable 0,00

No pictures to display