



PEUGEOT Boxer 335: 731BYQ

Vinnnumber:	VF3YCBMFB11842055	Versionname:	BOXER 335 B/F MWB HR L2H2 120pk
First Registrationdate:	19/08/2010	Fiscalpower:	
Expertise Mileage:	73941	Power Kw:	88
Bodytype:	Transporter	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	LCV15
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Windows electric F		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Halogen		
Type of GPS	No GPS		
Type of Lining	Lining fabrics		
Type of climate control	No climate control		

Limited Technical Inspection

Airco functioning	NOT OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/70/15/107 S Steel			
Summer tyres:	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1189,71
--------------------------	----------------

Bumper F, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Bodywork, Not original part, Acceptable	0,00
--	-------------

No pictures to display

Sidewall RL (LCV), Dent(s) and scratch(es), It - Spot repair	115,56
---	---------------









Rearview mirror housing L, Crack, E - Replace	64,00
--	--------------



Sill outer L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Roof pillar L, Dent(s) and scratch(es), LI - Repair and paint (complete)	165,14
	
Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)	217,56
	
Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	165,13
	
Bumper corner R L, Broken, E - Replace	108,00
	
Trunk door R L, Dent(s) and scratch(es), It - Spot repair	115,56
	
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	238,76
	
Sill outer R, Scratch(es), Acceptable	0,00

No pictures to display