



SKODA Octavia: 1GQV627			
Vinnumber:	TMBJG7NE5E0098897	Versionname:	OCTAVIA COMBI Ambition 105PK
First Registrationdate:	3/04/2014	Fiscalpower:	
Expertise Mileage:	175916	Power Kw:	77
Bodytype:	Break	Body color:	Beige
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1231
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control




























Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/55/16/91 W LightMetal			
	Fr.L.	Fulda: 8 mm	Fr.R.	Fulda: 8 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			653,80
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)			95,00



Alloy rim R R, Scratch(es), Acceptable	0,00
--	-------------

<i>No pictures to display</i>			
Seat adjuster F L, Missing, E - Replace			12,00
			
Bumper F, Scratch(es), LI - Repair and paint (complete)			211,80
			
			
Bumper R, Dent(s) and scratch(es), Le - Replace and paint			0,00
			
			
Door R R, Chemical polution, LI - Repair and paint (complete)			0,00
			
Rearview mirror housing R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Luggage space cover, Missing, E - Replace			240,00
			
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00
			
			
Wing R R, Scratch(es), LI - Repair and paint (complete)			0,00
			
Door F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Stone chip(s), Acceptable			0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00

