



**VOLKSWAGEN Golf: 1H5K666**

Vinnumber:	<b>WVWZZZAUZFP540542</b>	Versionname:	<b>GOLF VAR Trendline 105PK</b>
First Registrationdate:	<b>22/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>146158</b>	Power Kw:	<b>77</b>
Bodytype:		Body color:	<b>Silver</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3407</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>SD</b>	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>195/65/15/98 H Steel</b>			
Summer tyres:	Fr.L.	<b>Continental: 3 mm</b>	Fr.R.	<b>Continental: 3 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

**Assistance equipment**

















Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	766,36
-------------------	--------

Seat cover R L, Stain, Cleaning	12,00
---------------------------------	-------



Backrest cover F L, Damaged, E - Replace	360,00
--	--------

		Wheel cover F R, Scratch(es), E - Replace	30,00
		Seat cover R R, Stain, Cleaning	12,00
		Bumper R, Missing, E - Replace	25,00
		Windscreen, Stone chip(s), Windscreen repair	0,00
		Door F R, Bad repair, Acceptable	0,00
		Bumper F R, Scratch(es), It - Spot repair	115,56
		Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
		Bonnet, Dent(s), Acceptable	0,00
No pictures to display			
Rearview mirror housing R, Scratch(es), Acceptable			0,00
No pictures to display			