



VOLKSWAGEN Touran: 1DZW965			
Vinnnumber:	WVGZZZ1TZDW010766	Versionname:	TOURAN Trendline BMT Start/Stop 105PK
First Registrationdate:	21/09/2012	Fiscalpower:	
Expertise Mileage:	162187	Power Kw:	77
Bodytype:		Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3509
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 H Steel			
Winter tyres:	Fr.L.	Uniroyal: 8 mm	Fr.R.	Uniroyal: 8 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	1052,45
Wheel cover F R, Missing, E - Replace	0,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---------------



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	310,50
---	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Scratch(es), 67 - Polish 0,00

No pictures to display

Wheel cover R R, Missing, E - Replace 0,00



Wheel cover F L, Missing, E - Replace 0,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Wheel cover R L, Missing, E - Replace 0,00

