


TOYOTA AVENSIS TOURING SPORTS: 1PTZ930

| | | | |
|------------------------------------|--------------------------|--------------|-------------------------|
| Vinnumber: | SB1ET76L80E018244 | Versionname: | 2.0 D-4D PREMIUM |
| First Registrationdate: | 19/09/2016 | Fiscalpower: | |
| Expertise Mileage: | 28482 | Power Kw: | 105 |
| Bodytype: | Break | Body color: | Dark Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3311 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|------------------------------|------------------------------|
| Windows electric F | Seats electric F L |
| Windows electric R | Seats electric F R |
| Cruise Control | Central consol F |
| Steering wheel multifunction | Luggage cover |
| Seats F heated | Front parking sensors |
| Radio multimedia | Rear parking sensors |
| Type of headlighting | Headlighting Xenon |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining leather |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|--------------------------|-------|--------------------------|
| | 225/45/18/95 W LightMetal | | | |
| Summer tyres: | Fr.L. | Bridgestone: 4 mm | Fr.R. | Bridgestone: 4 mm |
| | Re.L. | Bridgestone: 5 mm | Re.R. | Bridgestone: 5 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|--|--------|
| Total cost ex VAT | 390,80 |
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Door F L, Repaired, Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wing R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Protection plate M, Strained , E - Replace | 84,00 |



| | |
|------------------------------|------|
| Bonnet, Repaired, Acceptable | 0,00 |
|------------------------------|------|

No pictures to display

no pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

211,80

